Under Review Notification

 Raised By: Vanessa Morel
 Product #: RBW109-3400-82-1

 Date: 2019.10.27
 Product Name: PUMP SEAL REMOVAL TOOL ASSY

		"Y" or "N" Required for Each Part							t		
		Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers		Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Enginer Signoff	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
RBW109-3400-82-1	RBW109-3400-82-1 Rev	Υ	Υ	Ν	Υ	Υ	Ν	Ν	Ν	19-987	See below

Description of Issue:

Issues stated on ADR (Fit issues, Qty must be changed)

RBW109-3400-82-1 and items -3, -5 and -7 must be put on **HOLD** in Plex

RBW109-3400-82-1 Finish good stock must be put in quarantine

Items -3, -5 and -7 stock must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: VP Operations Director of Engineering Customer Support Manager **Technical Support Director of Operations** Chief Engineer **Production Engineers** Product Manager - Solutions Provider **Director Quality Assurance Engineering Project Managers Production Planners** Supply Chain Director / Senior Buyer QC Coordinator **Engineering Clerk Purchasing Manager** Marketing Eugene